# Weathertzsiton Assistance Program

# Work Order Bid (ID)

### **WORK ORDER INFORMATION**

Work Order Name: 13013SH3473Work Order Type: WeatherizationAudit Name: 13013SH3473

### **CLIENT INFORMATION**

Client ID: 13013SH3473

### <u>AGENCY INFORMATION</u>

Client ID: 13013SH3473

Agency:Shelby County Community Services AgencyAgency Phone:(901) 222-4280Address:3772 South Hickory Ridge Mall, Suite 516Fax:(901) 222-4313

Memphis, TN 38115 Email Address:

Agency Contact: WOOD, JIM Work Phone:
Cell Phone:

Email Address:

Company Name & License Number:	
Contractor's Signature:	

### **COMMENT**

## Measures

M	leasure 1 Infilt	ration Redctn			Componer	its			Inspected
Comment CAULK STORM WINDOW #1  CAULK WINDOWS #4 AND #6  CAULK AND GLAZE WINDOWS #7,8,9 AND REMOVE AND REINSTALL  STORM WINDOW WHEN GLAZING THE WINDOW.  CAULK AND GLAZE WINDOW #11 AND REMOVE AND REINSTALL  STORM WINDOW WHEN GLAZING THE WINDOW  REPLACE WINDOW #11 SILL  INSTALL THRESHOLD AT SIDE DOOR  WEATHERSTRIP ATTIC STAIRS  BLOCK AND SEAL A/C UNIT COMPLETE IN WALL #2									
	BEGOIL	AND GEALT VO ONLY O	OWN ELTE	114 007	Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Miscellaneous Su	Infiltration Reduction	Each	1					
2	Labor	Infiltration Reduction	Each	1					
Ot	her Detail								
				Measur	e Sub Total:			Sub Total:	
F	Field Notes:								

	Measure 2 DWI	l Pipe Insulation			Componen	its			Inspected
C	<b>comment</b> WRAP \	WATER LINES 2 FT EAG	ND CC	DLD					
					Estimated	Actual			
#	Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
2	Labor	DHW Pipe Insulation	Each	1					
_	Other Detail								
				Measur	e Sub Total:		] ;	Sub Total:	
	Field Notes:								
		r Ins. R-19 L FLOOR INSULATION	925 SQ. F		Componen	ts FD1		ı	Inspected
			925 SQ. F		Componen  Estimated			Actual	Inspected
C			925 SQ. F <i>Unit</i> s		-		Qty		Inspected Total
C	<b>comment</b> INSTAL	L FLOOR INSULATION		T	Estimated	<u> </u>	Qty	Actual	
# 1	Comment INSTAL  Material / Labor	Description / Comment Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	Units	T Qty	Estimated	<u> </u>	Qty	Actual	
<b>#</b> 1	Comment INSTAL  Material / Labor Insulation  Labor	Description / Comment Floor Insulation - Fiberglass Batts - R-19	<i>Units</i> SqFt	<b>Qty</b> 925	Estimated	<u> </u>	Qty	Actual	
<b>#</b> 1	Comment INSTAL  Material / Labor  Insulation	Description / Comment Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	<i>Units</i> SqFt	<b>Qty</b> 925	Estimated	<u> </u>	Qty	Actual	
<b>#</b> 1	Comment INSTAL  Material / Labor Insulation  Labor	Description / Comment Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	<i>Units</i> SqFt	<b>Qty</b> 925	Estimated	<u> </u>	Qty	Actual	
<b>#</b> 1	Comment INSTAL  Material / Labor Insulation  Labor	Description / Comment Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	<i>Units</i> SqFt	<b>Qty</b> 925	Estimated	<u> </u>		Actual Unit Cost	
<b>#</b> 1	Comment INSTAL  Material / Labor Insulation  Labor	Description / Comment Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	Units SqFt SqFt	<b>Qty</b> 925 925	Estimated	<u> </u>		Actual	
<b>#</b> 1	Comment INSTAL  Material / Labor Insulation  Labor	Description / Comment Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	Units SqFt SqFt	<b>Qty</b> 925 925	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
<b>#</b> 1	Material / Labor Insulation Labor  Cother Detail	Description / Comment Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	Units SqFt SqFt	<b>Qty</b> 925 925	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

Measure 4 Wall Insulation				Components WL1,WL10,WL11,W Inspect L12,WL2,WL7,WL8, WL9					
Comment ADD R-	13								
				Estimated			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	888						
2 Labor	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	888						
Other Detail									
			Measu	re Sub Total:			Sub Total:		
	Monitor is Needed L 2 CO.MONITORS			Componer				Inspected	
# Material / Labor	Description / Comment	Units	Otv	Estimated Unit Cost	Total	Otv	Actual Unit Cost	Total	
Health and Safety	-	Each	<b>Qty</b> 2		TOTAL	Qty	Omit Cost	IOlai	
2 Labor	Labor	Each	2						
Other Detail						7			
			Measu	re Sub Total:			Sub Total:		
Field Notes:									

Measure 6 Fix Any Other Venting Related Problem (Water Heat)			Components				Inspected	
Comment REVENT	Γ W/H FLUE 15 FT THR	U ROOF						
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
1 Health and Safety	Equipment	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
			Measu	re Sub Total:			Sub Total:	
	mproper Venting (Clot)	•		Componen CT TO VENT Estimated			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety		Each	1					
2 Labor	Labor	Each	1					
Other Detail								
Field Notes:			Measu	re Sub Total:			Sub Total:	

	Measure 8 Pres	sureRelief Piping Need	ded		Componen	its		ı	nspected
C	<b>Comment</b> REPLAC	E DROP ON T&P VAL	/E.						
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Pressure relief piping	Each	1					
2	Labor	Labor	Each	1					
(	Other Detail						,		
				Measur	e Sub Total:		] ;	Sub Total:	
	Field Notes:								
l									
			Work Or	der Gra	nd Total:		Gran	d Total:	

Client ID: 13013SH3473